

三针压力表

Three-pointer Pressure Gauge

产品应用 Product Application

本系列仪表是为满足工艺条件对生产操作人员进行提示而制作的，黑针提示实测压力值，红针指示工艺条件允许的最高压力值，绿针指示工艺条件允许的最低压力值，正常生产时，黑针在红针及绿针中间指示，若超出红针或绿针范围，则表示工艺生产异常，提醒操作人员及采取措施，以保证安全生产。

This series of instruments is designed to provide prompts to production operators based on process conditions. The black needle indicates the actual measured pressure value, the red needle indicates the maximum allowable pressure value according to the process conditions, and the green needle indicates the minimum allowable pressure value according to the process conditions. During normal production, the black needle should indicate between the red and green needles. If the pressure exceeds the range indicated by the red or green needle, it indicates an abnormality in the process production, prompting the operator to take necessary measures to ensure safety in production.



技术参数 Main Technical Specifications

型号 Model	测量范围 MPa Measurement Range	精度等级 Accuracy Grade
YB-100 YB-150 YB-200 YB-250	-1~0、-0.1~0.06、-0.1~0.15、-0.1~0.3、-0.1~0.5 -0.1~0.9、-0.1~1.5、-0.1~2.4、-0.1~3.9、-0.1~5.9 0~0.6、0~1、0~1.6、0~2.5、0~4、0~6 0~10、0~16、0~25、0~40、0~60、0~100 0~160、0~250、0~400、0~600、0~1000	1.0, 1.6, 2.5